


Legend	
	Surveyed edge of water
	Existing contour
	Cross section
	Proposed bank
	Coir lift bank protection
	Rock toe bank protection

- Notes:
- Total Station survey of shore and top of bank completed by Matrix Solutions Inc. on November 3, 5, 2015 and June 1, 2016
 - Bathymetric survey completed by Matrix Solutions Inc. on November 3, 4, 5, 2015.
 - Elevations displayed on figure are based on meters above sea level +100m.



Anqotum
Resource Management

Fisheries and Oceans
Canada

REVISION					
No.	DATE	DESCRIPTION	BY	CHK.	DRN.
01	13 05 2016	Draft for client review	ESD	RJ	ESD

Small Craft Harbours

**Little Southwest Miramichi River
Bank Restoration Design
Plan View**

Date:	13 05 2016	Project:	22751	Technical:	E. Drost	Reviewer:	R. Jenkins	Drawn:	E. Drost
-------	------------	----------	-------	------------	----------	-----------	------------	--------	----------

Disclaimer: The information contained herein may be compiled from numerous third party materials that are subject to periodic change without prior notification. While every effort has been made by Matrix Solutions Inc. to ensure the accuracy of the information presented at the time of publication, Matrix Solutions Inc. assumes no liability for any errors, omissions, or inaccuracies in the third party material.

01